

SAFE WORK PROCEDURE

Shop Vac Page 1 of 2

LOCATION OF WORK:	WRITTEN BY:	APPROVED BY:	DATE:	LAST REVISION:
All Buildings	L. Carriere	Safety Committee	September 4, 2014	March 8, 2017

HAZARDS PRESENT	PERSONAL PROTECTION EQUIPMENT (PPE)	ADDITIONAL REQUIREMENTS
 Eye injury – sawdust, flying debris Eye Irritation Dust inhalation Noise 	Safety glassesProtective footwearProtective glovesHearing protection	 Equipment Orientation Approved Dust Mask (N95), may be required

SAFE WORK PROCEDURE

PRE-OPERATIONAL SAFETY CHECKS:

- 1. Inspect required personal protective equipment and replace if required.
- 2. Ensure no slip/trip hazards are present in workspaces and walkways.
- 3. Make sure guards, if present, are installed and are working properly.
- 4. Faulty equipment must not be used. Immediately report suspect machinery.
- 5. Locate and ensure you are familiar with the operation of the ON/OFF starter.
- 6. Do not use equipment with open sources of ignition (Fire / Explosion Hazard)
- 7. Do not leave this equipment unattended while running
- 8. Do not vacuum anything that is burning or smoking, such as: matches, hot ashes.
- 9. Do not vacuum toxic materials.
- 10. Do not lift a vac that is heavy with liquid or debris.
- 11. Do not use blower for any job except blowing dirt and debris.
- 12. Do not direct air at bystanders.

SAFE WORK PROCEDURE:

- 1. Put on all required personal protective equipment (PPE).
- 2. Determine if the vacuum will be used as a wet or dry vac and make all adjustments with POWER OFF.
- 3. Make sure the lid is in place, properly adjusted, and secured.
- 4. Select and securely attach appropriate accessory for the job
- 5. Securely connect hose to either vacuum or blower port.
- 6. Turn ON and perform operation.
- 7. Turn OFF when completed.
- 8. Drain or empty drum by rolling the vac to the garbage or drain. Remove the lid and using appropriate lifting techniques, empty the vac.
- 9. Clean the interior of the drum and replace the lid.
- 10. Return the vacuum to the appropriate storage location.
- 11. Store hoses and accessories with POWER OFF.

SAFE WORK PROCEDURE

Shop Vac Page 2 of 2

HOUSEKEEPING:

- 1. Ensure equipment is off.
- 2. Place all materials in their proper storage areas.
- 3. Ensure the equipment is safe, clean and tidy before you leave it.

REGULATORY REQUIREMENTS

- WS&H Act W210, Section 4, 5, 7, 7.1
- MB. Regulations 217/2006,
 - o Part 2, Section 2.1 Safe Work Procedures
 - o Part 6, Section 6.1 PPE
 - o Part 8, Musculoskeletal Injuries
 - o Part 12, Section 12.3, Hearing Protection
 - o Part 16, Sections 16.1 16.18, Machine & Tool Safety
 - o 35.0 WHMIS
 - o 36.0 Chemical Biological Substances
- WS&H Act W210, Section 4, 5, 7, 7.1
- Operators Manual